

1/5

FIG 1





FIG 2






FIG 4




FIG 5A

Start: CLK=0 & Q=0




FIG 5B




FIG 5C




FIG 5D




FIG 5E




FIG 6

